



RDX

Type: POWDERS AND EXPLOSIVES

Hexogen is used to fill the fuse caps and for the manufacturing of detonating cords, detonators and mines. Civil and military destination.

General characteristics:

Appearance fine white crystals

Melting point min. 200° C

Ash max. 0,05%

Acidity (as HNO₃) max. 0,05%

Granulation



Thru US STD Sieve,%0	Class 1		Class 3		Class 4		Class 5	
	min.	max.	min.	max.	min.	max.	min.	max.
8								
12								
20	96	100						
35					0	40		
50	80	100	30	50				
100	30	90	10	30				
200	5	45	0	20				
325							97	-